UI Bulletin #154

Subject:	Upfit Body Mounting / Chassis Wiring Harness Routing
Models:	Chevrolet Silverado/GMC Sierra 3500 HD Cab Chassis Models only
Model Years:	2011 and Beyond
Date:	July 19, 2019
Revision Date	N/A

ADVISORY:

This GM UI Bulletin is designed to assist upfitters with upfit body to frame interface regarding the rear chassis wiring harness on C/K HD Cab Chassis models

Condition/Concern:

Care must be taken when installing upfit bodies on the rear driver's side chassis to allow clearance to wiring harness/attachments. Wiring Harness `Service Access' could be compromised when mounting an upfit body. Upfit Body mounting provisions should not pinch or lock in the OEM harness/attachments.



Figure 1 Harness Area of Concern

Disclaimer: GM Upfitter Integration Technical Bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service and/or modification of a vehicle. These properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. Contact GM Upfitter Integration for information on whether the information is applicable your vehicle.

Recommendation:

Upfit body mounting practices and provisions should allow for service of chassis wiring harness/attachments.

If the upfitter chooses to relocate the harness inboard, they're responsible for the proper securing and protection of the harness. Similar OEM harness support intervals should also be utilized. Care should be taken so harness does not chafe sensitive chassis lines, components and modules**.**

Additional Information:

Refer to GM UI BEST PRACTICES `CHASSIS' & `ELECTRICAL' Sections regarding serviceability, routing and securing chassis wiring harnesses. http://www.gmupfitter.com

Disclaimer: GM Upfitter Integration Technical Bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service and/or modification of a vehicle. These properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. Contact GM Upfitter Integration for information on whether the information is applicable your vehicle.